the audject violations/ correct!

Deing done and we waited and waited and nothing came, so that is when we issued a summons. I forget who I talked to. I think it might have been Mary Beth --

Q You really have to speak up we can't hear you.

A I spoke to Mary Beth. I think she had intervened at some point and said that the engineer's report was coming and it took too long, so we just issued the summons. Again, we are willing to work with the people.

MRS. FIORE: No further questions at this time.

MRS. MULLINS: No recross.

THE COURT: Do you wish to excuse

Mr. Carpaneto?

MRS. FIORE: Yes, with the possibility of recalling him.

THE COURT: Okay. Call your next witness.

MRS. FIORE: We call Anthony Oliveri.

THE COURT: I will swear you in.

A N T H O N Y O L I V E R I, a witness herein,

1.4

```
having been first duly sworn by the Court, was
4
      examined and testified as follows:
2
      EXAMINATION BY MRS. FIORE:
3
                       Good morning, Mr. Oliveri.
4
                       Good morning.
                A
5
                       Mr. Oliveri, could you please state
                0
6
       for the record your current place of employment?
7
                        Dolph Rotfeld Engineering.
                Α
8
                        How long have you been employed by
9
       Dolph Rotfeld?
10
                        Just about ten years.
                Α
11
                        What are you your duties in
                Q
12
       connection with Dolph Rotfeld?
13
                        Project manager.
14
                        What are your duties as the project
15
       manager?
16
                        I supervise other engineers,
                 А
17
       technicians for different projects that we have,
18
       one of them being the town engineer for the Town of
19
       Mamaroneck.
20
                        Are you an engineer yourself?
21
                        Yes.
                 Α
22
                         Do you have a degree in connection
                 Q
23
        with that title?
24
                         A Bachelor of Science in Aero Space
                 Α
25
```

Engineering Polytec University. 1 What year did you receive that 2 3 degree? 1989. Α 4 Have you received any other formal 5 Q education beyond that degree? 6 7 Α No. Could you briefly state and 8 summarize your engineering, whether it be 9 employment or of course work or anything of that 10 nature? 11 After graduating, I worked for a 12 13 small firm in Eastchester. We did mostly residential work, civil engineering work, some 14 structural work on a residential level. 1997, I 15 went to work for an engineering company where I 16 started as a project engineer and now I'm a 17 18 manager. In 1995, I received my license in 19 engineering from New York State. I am a licensed 20 professional engineer. I did take some courses in 21 preparation for that. 22 What is a licensed engineer 23 24 qualified to do? A licensed engineer is qualified to 25 Α

assign and seal certified plans for buildings or 1 any other kind of construction, municipal work, for 2 instance requires professional engineer signature 3 and seal beyond the plans, private work would be a 4 house or something like a retaining wall, where you 5 have to get a building permit, you would need a 6 professional engineer's certification. 7 MRS. FIORE: Your Honor, at this 8 time I move to qualify Mr. Oliveri as an 9 expert in engineering. 10 MRS. MULLINS: Your Honor, with all 11 due respect to Mr. Oliveri, I don't believe 12 that the District Attorney's elicited --13 MRS. FIORE: Town prosecutor. 14 MRS. MULLINS: Town prosecutor, 15 elicited the appropriate and sufficient 16 information to have him qualified. 17 MRS. FIORE: He is a licensed New 18 York State Engineer. 19 THE COURT: That is correct and I'm 20 not going to second guess The New York 21 State Department of State and I qualify Mr. 22 Oliveri as an expert in engineering as it 23

relates to residential circumstance.

MRS. MULLINS: Yes, Your Honor.

24

25

HE I SE TEE TO BE BENET

11

2	Q Mr. Oliveri, approximately, have saily
3	home inspections, if you know, have you performed
4	personally?
5	A How many inspection, when you say
6	home inspections, that is kind of a different type
7	of thing. Just maybe a site inspection, is that
8	what you mean?
9	Q Yes, sorry?
10	A Probably hundreds.
11	Q Over five hundred?
12	A I don't know if it's over five
1.3	hundred, it could be.
14	Q Over three hundred?
15	A Probably.
16	Q And have you performed engineering
17	services for the Town of Mamaroneck prior to this
18	occasion?
19	A Yes.
20	Q On how many occasions?
21	A It is on a continuing basis, we are
22	lating ongineers
23	The sompostion with your consulting
2 4	
	Huguenot?
2 5	CO ATRIC ETC.

Could you explain to the Court exactly what you did in connection with that? MRS. MULLINS: Could we have a time frame? THE COURT: Yes. I believe it was October 25th, it was, I believe, the day before I issued my statement, my report. Ron Carpaneto, the building inspector, called and asked me to come and take a look at the wall. I went out and met him. We looked at the wall, measured it, looked at it form both sides actually --When you say both sides, what is the other side? From 2 Lafayette and also from 5 Α Huquenot. So you were on both sides of the Q subject wall; is it fair to say that? That is right and he asked me to issue a report.

Document 11:

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Q After you received the call from Mr. Carpaneto, did you go to the premises of 5 Huguenot Drive?

A Yes.

Did you observe the wall? 1 Yes. A 2 Could you tell the Court what you 3 0 observed? 4 What I saw was -- it seemed to be an 5 A older stone and water retaining wall, which was 6 approximately fifteen feet high at the highest 7 point, which had a vertical crack about mid span of 8 the wall and it also had some evidence of-- well 9 there were tie back plates on the stone wall, which 10 were severely rusted. 11 Excuse me, you said the wall at 12 it's highest height was fifteen feet? 13 The stone wall, on top of that was 1 4 the block wall, a concrete block. 15 That was the height and how long 16 17 was the wall? I did not measure the length. 18 Do you recall? 19 Q Approximately, I would say forty 20 feet, maybe. 21 In length? 22 Q Yes, I did not measure it. I only 23 measured the height at one point. 24 When you say the top of the wall, 25

2.3

that you refer to as concrete block, could you explain what you are referring to?

A Approximately five feet of concrete block wall seemed to have been built on top of the stone wall. It did not seem to be original to the wall or built at the same time as the stone wall. The block wall had a number of cracks.

It seemed to be leaning slightly outward. You could tell by just the alignments of the wall by looking at it. It also seemed to be overhanging at one point where the stone wall had a slight bend, the block wall was overhanging about three to five inches. I did not measure it. I could not get up to that point but visually you could see the overhang.

There were plates, steel plates on the wall, which indicated that there were tie backs at some point installed.

O What is a tie back?

A That is something that consists of a steel plate and a steel rod, which is driven through the wall. At the end of the rod it might have a screw type mechanism or something to anchor it into the soil behind the wall.

I was not sure really if this was

7:08:cv:04703-SCR Document:11 Filed:07/01/2008 Page:9 of

2.1

or maybe afterwards to stabilize it, you really could not tell. But the wall at some point had moved away from the lower wall and, you know, was leaning slightly.

The return part of wall that went perpendicular to the property line had a poured concrete wall, which was straight an true with the stone wall. The concrete block wall had some issues happening.

You were describing and I interrupted you but you were describing the condition of the tie backs?

The tie backs on the stone wall, the lower wall, were severely rusted even Ron and I were able to chip off little pieces with our fingernails. Those were most likely installed sometime after the crack happened in the lower stone wall.

Q Described the crack you are referring to now?

A The stone wall about mid span or mid length had a crack, which went from the bottom of the wall to the top of the stone wall where the concrete block wall began.

Q It can the entire length of the * stone wall? 2 MRS. MULLINS: Height. 3 Yes, it ran the entire height of 4 the stone wall? 5 Yes and the tie backs seemed to be 6 on either side of the crack and must have been put 7 in to stabilize that crack but they were very 8 rusted and how long they are going to last, I don't 9 know. I think there was some patch material in the 10 crack also, somebody tried to patch this crack. 11 When this was done, the concrete block wall was in 12 place at the time, that is anyone's guess. 13 What happens when steel tie backs 14 used to support the wall or crack, were to continue 15 to rust through as you described? 16 Well, if they were placed there to 17 stabilize the stone wall, if they rusted through, 18 then they have no more structural significance. 19 What would the purpose be other 20 than supporting the stone wall? 21 There would be no other purpose A 22 that I know of. 23 How many tie backs did you observe 24 on the stone wall? 25

dealt have a number. than three, maybe four. Ź Were they also in the same 3 condition? 4 It seemed to be. 5 Α Rusted? 6 0 7 Α Yes. What other observations did you 8 Q make? 9 On the stone wall or on the entire A 10 wall? 11 Not the perpendicular wall that you 12 0 13 said was straight and true but the retaining wall? The block wall, like I said, had 14 Α 15 seemed to move at some point. There was a gap also where the block wall joined the stone wall, there 16 17 was a gap there. There might have been water in 18 there at some point that washed out when the wall 19 shifted, maybe it fell out. Like I said, there were 20 21 steel tie back plates, which were large plates and 22 again, I don't know if those were original to the 23 design or installed afterwards to stabilize the wall, I don't know. 24 25 Q What was the condition of those tie

1	leaning and has an overhang and to me, that is a
2	failed design.
3	MRS. FIORE: Thank you, I have no
4	more questions at this time.
5	THE COURT: Mrs. Mullins, do you have
6	cross examination?
7	MRS. MULLINS: Yes.
8	CROSS EXAMINATION BY MRS. MULLINS:
9	Q Good morning, Mr. Oliveri.
10	A Good morning.
11	Q Do you have any notes from your
12	field visit to the site, any hand-written notes?
13	A I have something, I do have
14	something back at the office, one sheet where I
15	just did a quick sketch.
16	Q Did you take any photographs?
17	A No.
18	Q You testified that you took
19	measurements that day; is that right?
20	A Yes, I took one measurement at the
21	corner of the wall at the highest point to get a
22	sense of the height of the wall and the height of
23	the concrete block.
24	Q Is that the only measurement you
25	took?

In your experience, could you 2 estimate for me the age of the lower stone portion 3 of the wall? 4 5 Α No. Could you give us some 6 7 indication --I have no idea, it's old, that is 8 9 all I could say. Would you say it's probably 10 11 original to the construction of the homes there? I have no idea. 12 With regard to the upper block 13 portion, could you give us an estimate that --14 The only thing I could say about 15 16 the age is because it's of different construction, it seems to be done after the stone wall. 17 And you testified with regard to 18 19 the tie back and so that we are all clear, there are two sets of tie back, there are tie backs in 20 the stone portion of the wall and there are tie 21 backs in the upper block portion? 22 23 A Yes. So your testimony is that the tie 24 backs that are in the stone older portion of the 25

1 wall are rusted? 2 Right. 3 0 And further it's your testimony 4 that they probably don't have any useful value any 5 longer? 6 MRS. FIORE: Objection. 7 THE COURT: Overruled, could you 8 answer at question. 9 Yes, there are rusting. They may 10 still have some value. When they fully rust 11 through, then the structural value will be gone. 12 What is your opinion as to the 13 structure integrity of the bottom of the wall? 14 A The bottom stone wall seems to be 15 straight. It did not seem to be leaning. The tie 16 backs that were put in may have stabilized, that 17 crack seemed like an old crack and not something 18 new, so, you know, I did not see any immediate 19 problems with the stone part of the wall, it was 20 more concentrated on the concrete of the wall. 21 In your opinion, the stone wall 22 bottom portion is it in acceptable condition? 23 It seemed to appear that way. A 24 0 And further you testified that now 25 with regard to the block portion of the wall, five

feet you testified that is how high it is, is it 1 five feet continuously through it's length? 2 It was five feet at the corner that 3 is where I measured it. It might have tapered 4 slightly as it went, maybe it was to the left. 5 When you look at it, it tapers down 6 to the left? 7 Right. A 8 Is it your testimony that the steel 0 9 tie backs that were installed in the block portion 10 are in good condition? 11 They seem to be. 12 And you are not sure, are you 0 13 whether they were installed during the original 14 construction of that block wall or sometime after; 15 is that true? 16 That is true. 17 Is it true that those steel tie 18 backs could have been installed to repair the 19 condition that was apparent to that stone block 20 portion? 21 They could have been installed to A 22 stabilize it. 23 Could you describe for the Court 24 how big those steel plates are? 25

A I believe they wate at least one 1 foot square plates, how long the rods were, I don't 2 3 know. How many were there, if you recall? 0 4 At least two, maybe three or four. Α 5 Normally, the rod that you 6 testified that was attached to that large steel 7 plate, how long are they normally? 8 It all depends on the design. 9 What are they normally designed to 0 10 do? 11 To keep the wall from tipping over 12 and this why I said it could be original and it may 13 not be, being that the block wall was built on top 1 4 of the stone wall, it would have a typical type of 15 footing, they might have put it in originally to 16 keep it from tipping and that is why I can't say 17 either way. 18 MRS. MULLINS: I move to strike as 19 unresponsive. 20 THE COURT: It is not stricken. 21 I'm asking you with regard to that 0 2.2 rod that is attached, what factors vary on how long 23 those rods are? 24 The soil conditions and the height 25

2 With a five foot wall, how long 3 should that rod be? To the answer that, it would have Α 4 to be designed by a professional engineer. 5 Such as yourself? 6 Yes or somebody who specializes in 7 that type of thing. 8 The last part of your testimony was 9 10 with regard to your opinion as to the structural stability of that block portion; is that right? 11 12 Yes. You testified that there was 13 14 clearly, in your mind, evidence of movement, 15 although you are not sure when that movement took place; correct? 16 17 Α Yes. 18 And that, in your mind, movement means -- well, tell me what does that mean? 19 20 In my mind or any engineers mind, 21 if a retaining wall moves, it failed. A retaining 22 wall is not designed to move. 23 Is it possible that after your inspection of the wall, that the movement that has 24 25 occurred in that wall was remedied by the

contactation of their tip because

No.

2

A I don't know herause & don't know

if they were original or not.

Q Could you estimate for us when that

movement took place?

Q Does it appear to you, after your inspection of the premises, that it is a resent event?

A No.

Α

Q So tell me what is not resent to you, years, more than five years, more than ten?

A It's impossible to say, it did not happen last week, it was not fresh.

O Or last month?

A Right.

Q Mr. Oliveri, after you prepared your written report for the Town of Mamaroneck's Building Department, did you have some recommendations to them with regard to some further action by the town?

A We recommended that a structural engineer do a full evaluation of the wall and that also recommended that no vehicle park adjacent to the top of the wall.

Ara you avera that the Catacolom

in this case, the home owners, installed car stops on the upper --

2.0

A Yeah, I saw them when I was there.

Q Did you have any recommendations for the building department with regard to what other measures should be taken with regard to this wall?

A No, just that a structural engineer evaluate it.

Q Is it your opinion that you are not qualified to give an opinion with regard to the structural integrity of the wall?

A No, but in a case like this -
MRS. FIORE: No, it's not your

opinion or no you are not --

THE COURT: You are not objecting, so let the witness answer the question.

A It's not my opinion that I'm not qualified any P.E. would be qualified to make a statement about the wall, but we just felt that a structural engineer, somebody that specializes in retaining walls would be better suited to be give a more thorough evaluation and examination.

MRS. MULLINS: I have nothing